Service Bulletin

SB No. TR04080401N

Original Date	Revised Date	Problem Code	Type Code	Status	Author
AUG 4, 2004	-	-	-	New	KING

Subject: Treadmills - New Frame Design

Serial Number: See chart below

Time Required: ☐15 min ☐30 min ☐45 min ☐1 hr +

Distribute To: X Internal ☐Dealer ☐ISO ☐Customer

GENERAL:

Treadmill frame design incorporates new Belt Barrier Tracking System. See table below for affected model treadmills.

Model No.	Serial Number
97Te	TTM100130-Above
97Ti	TTO101872-Above
95Te	TTE100469-Above
95Ti	TTJ116896-Above
93T	TTD105031-Above



Life Fitness Proprietary and Confidential Information - Only for the Use of the Intended Recipient - Do Not Reproduce or Distribute.